

From: S. S. Liou [ssliou@seed.net.tw]  
Sent: Wednesday, April 30, 2003 1:53 AM  
To: Mike Kuo  
Subject: Re: Chung-Hsin Electric & Machinery Mfg. Corp., FCC  
ID:QWTVS5811R, AN03T2694

Hi Mike,

For your questions,

1. Please refer to revised test report. The description of transmission time is corrected.
2. Please refer to revised ID label.

regards,

S. S. Liou  
Engineer / EMC Dep. II  
ETC

----- Original Message -----

From: "Mike Kuo" <MKUO@CCSEMC.com>  
To: "ETC/Iris (E-mail)" <etcemi@seed.net.tw>; "Will Yauo (E-mail)" <willyauo@seed.net.tw>  
Sent: Friday, April 25, 2003 5:36 AM  
Subject: FW: Chung-Hsin Electric & Machinery Mfg. Corp., FCC ID:QWTVS5811R, AN03T2694

>  
>  
> -----Original Message-----  
> From: CERTADM  
> Sent: Thursday, April 24, 2003 2:35 PM  
> To: 'mkuo@ccsemc.com'  
> Subject: Chung-Hsin Electric & Machinery Mfg. Corp., FCC ID:QWTVS5811R, AN03T2694  
>  
>  
> Notice\_content  
> -----  
> Question #1: Page 12 section 4.5 of test report indicates the "This Panic Watch is operated by Manual, and Activate Time is less than 5 second after being released" What is this Panic Watch in associated with the device ?  
>  
> Question #2: The FCC ID number listed in the proposed FCC ID label format does not agree with the one listed in the TCB application form. Please provide revised FCC ID label format.  
>  
> Best Regards  
>  
> Mike Kuo  
> The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information within 60 days of the original e-mail date may result in application dismissal and forfeiture of the filing fee. Also, please note that partial responses increase processing time and should not be submitted.

> Any questions about the content of this correspondence should be directed  
to  
> the e-mail address listed below the name of the sender.