

Update Explanation:

This update is to include the following changes:

1. The test samples received for testing was mistakenly set to an experimental modulation and not the modulation specified by the manufacturer for this product. Therefore the conducted antenna port measurements were repeated using the correct modulation bandwidth and inserted into Revision A of the Test Report.
2. There is an updated label format for the EA2W and EA2W-I. This label format is included in the update.
3. Several minor typos were corrected.
4. The Manufacture's Attestation Statement was added on page 2 of the report(s).