

Report No.: ER/2005/B0019 **Issue Date: Dec. 07, 2005**

APPENDIX 2 PHOTOGRPHS OF EUT



Report No.: ER/2005/B0019 **Issue Date: Dec. 07, 2005**

All of EUT




Front View of EUT





Report No.: ER/2005/B0019 **Issue Date: Dec. 07, 2005**

Back View of EUT



Left View of EUT





Report No.: ER/2005/B0019 **Issue Date: Dec. 07, 2005**

Right View of EUT



Top View of EUT





Report No.: ER/2005/B0019 **Issue Date: Dec. 07, 2005**

Bottom View of EUT



Adaptor-3DS09371AGAA Supplier: Leader Electronics





Report No.: ER/2005/B0019 **Issue Date: Dec. 07, 2005**

Adaptor-3DS09371AGAA Supplier: Astec



Adaptor-3DS09371AAAA Supplier: Astec





Report No.: ER/2005/B0019 **Issue Date: Dec. 07, 2005**

Adaptor-3DS09371AGAA Supplier: Leader Electronics



Adaptor-3DS07848AAAA Supplier: Primax





Report No.: ER/2005/B0019 **Issue Date: Dec. 07, 2005**

Open View of EUT



Internal of EUT --- 1






Report No.: ER/2005/B0019 **Issue Date: Dec. 07, 2005**

Internal of EUT --- 2




Internal of EUT --- 3





Report No.: ER/2005/B0019 **Issue Date: Dec. 07, 2005**

Internal of EUT --- 4



Internal of EUT --- 5





Report No.: ER/2005/B0019 **Issue Date: Dec. 07, 2005**

Internal of EUT --- 6

