




DH1\_Ant1\_2441\_1000~26500




DH1\_Ant1\_2480\_0-Reference




DH1\_Ant1\_2480\_30-1000




DH1\_Ant1\_2480\_1000~26500




2DH1\_Ant1\_2402\_0~Reference




2DH1\_Ant1\_2402\_30~1000




2DH1\_Ant1\_2402\_1000~26500




2DH1\_Ant1\_2441\_0~Reference




2DH1\_Ant1\_2441\_30~1000




2DH1\_Ant1\_2441\_1000~26500



2DH1\_Ant1\_2480\_0~Reference




2DH1\_Ant1\_2480\_30~1000




2DH1\_Ant1\_2480\_1000~26500







3DH1\_Ant1\_2402\_0~Reference




3DH1\_Ant1\_2402\_30~1000




3DH1\_Ant1\_2402\_1000~26500




3DH1\_Ant1\_2441\_0~Reference




3DH1\_Ant1\_2441\_30~1000




3DH1\_Ant1\_2441\_1000~26500




3DH1\_Ant1\_2480\_0~Reference



3DH1\_Ant1\_2480\_30~1000





3DH1\_Ant1\_2480\_1000~26500



## APPENDIX A: PHOTOGRAPHS OF TEST SETUP


### Radiated Spurious Emissions








**Conducted Emissions at AC Power Line (150kHz-30MHz)**




## APPENDIX B: PHOTOGRAPHS OF EUT











































----END OF REPORT----

The test report is effective only with both signature and specialized stamp, The result(s) shown in this report refer only to the sample(s) tested. Without written approval of BlueAsia, this report can't be reproduced except in full.