




DH1_Ant1_2441_30~1000




DH1_Ant1_2441_1000~26500




DH1_Ant1_2480_0~Reference




DH1_Ant1_2480_30~1000




DH1_Ant1_2480_1000~26500




2DH1_Ant1_2402_0-Reference




2DH1_Ant1_2402_30~1000




2DH1_Ant1_2402_1000~26500




2DH1_Ant1_2441_0~Reference






2DH1_Ant1_2441_30~1000







2DH1_Ant1_2441_1000~26500




2DH1_Ant1_2480_0-Reference









3DH1_Ant1_2441_30~1000




3DH1_Ant1_2441_1000~26500




3DH1_Ant1_2480_0-Reference



3DH1_Ant1_2480_30~1000




3DH1_Ant1_2480_1000~26500



APPENDIX A: PHOTOGRAPHS OF TEST SETUP


Antenna Requirement




Conducted Emissions at AC Power Line (150kHz-30MHz)



Radiated Spurious Emissions



APPENDIX B: PHOTOGRAPHS OF EUT






































----END OF REPORT----

The test report is effective only with both signature and specialized stamp, The result(s) shown in this report refer only to the sample(s) tested. Without written approval of BlueAsia, this report can't be reproduced except in full.