




October 21, 2019

Regarding ROR00000006 Part 96 application:

There is no tuneup procedure provided to the installer or user of the device. Tuning is performed at the factory.

Sincerely,

A handwritten signature in blue ink, appearing to read "Jim Dickerman". The signature is fluid and cursive, with the first letter "J" being particularly large and stylized.

Jim Dickerman

Vice President of Engineering

BLiNQ Wireless