

Attestation Letter

Date: May 17, 2012

Federal Communications Commission
Authorization and Evaluation Division

SUBJECT: ATTESTATION FOR THE MODIFICATIONS ON THE EUT
FCC ID: RTQKSCCCBR400A

To whom it may concern:

The circuit diagram and part list has been changed according to the test results. For detailed information, please refer to the followings;

CPU part modification		
Before	After	Remark
R53(22R)	BF13(MMZ1005Y102C)	Change of Component
R55(22R)	BF14(MMZ1005Y102C)	Change of Component
BF1(HB-1S3216-121JT)	BF1(NFM31PC276B0J3)	Change of Component
BF2(HB-1S3216-121JT)	BF2(NFM31PC276B0J3)	Change of Component
N/A	TC23(10uF/16V)	Addition of Component
N/A	C152(100nF)	Addition of Component
N/A	BF18 ~ BF39(MMZ1005Y102C)	Addition of Component
N/A	BF15(MPZ1608S121A)	Addition of Component
N/A	C268(10uF/16V)	Addition of Component
R423(0R)	BF17(MPZ1608S121A)	Change of Component
R425(0R)	BF8(MPZ1608S121A)	Change of Component
R23(22R)	R23(47R)	Change of Component
R24(22R)	R24(47R)	Change of Component
R14(22R)	R14(100R)	Change of Component
R15(22R)	R15(100R)	Change of Component
R76(22R)	R76(100R)	Change of Component
R79(22R)	R79(100R)	Change of Component
R369(0R)	R369(100R)	Change of Component
R371(0R)	R371(100R)	Change of Component

----- Next page -----

SUB Main part modification		
Before	After	Remark
R7(0R)	BF18 (MPZ1608S121A)	Change of component
R10(0R)	BF19 (MPZ1608S121A)	Change of component
R16(0R)	BF20 (MPZ1608S121A)	Change of component
R18(0R)	BF21 (MPZ1608S121A)	Change of component
N/A	BF25 (MPZ1608S121A)	Addition of Component
N/A	C18(100nF)	Addition of Component
R5(0R)	BF22 (MPZ1608S121A)	Change of component
R6(0R)	BF23 (MPZ1608S121A)	Change of component
N/A	BF24 (MPZ1608S121A)	Addition of Component
N/A	C19(10uF)	Addition of Component
N/A	BF26(HB-1S3216-121JT)	Addition of Component
AR20(22R)	BF27 ~ BF30(MMZ1005S102C)	Change of component
R176(22R)	BF31(MMZ1005S102C)	Change of component
BF5,BF7(HB-1S3216-121JT)	BF5,BF7(0R)	Change of component
N/A	RR193 ~ RR196	Addition of Component
R159,R163(Z_0R)	R159,R163(MMZ1005S102C)	Change of component
N/A	BF39,BF40,BF32,BF33,BF34 (MMZ1005S102C)	Change of component
R158(0R)	BF38(MMZ1005S102C)	Change of component
R175(0R)	BF37(MMZ1005S102C)	Change of component
R157(0R)	BF35(MMZ1005S102C)	Change of component
R174(0R)	BF36(MMZ1005S102C)	Change of component
R161,R178(1K)	R161,R178(Z_1K)	Change of component
R181,R165(4.7K)	R181,R165(Z_4.7K)	Change of component
R182,R166(100R)	R182,R166(Z_100R)	Change of component
Q9,Q10(KTD1304)	Q9,Q10(Z_KTD1304)	Change of component
N/A	D18,D19 (Z_CDSOD323-T03C)	Addition of Component
N/A	BF41(HB-1S3216-600JT)	Addition of Component
N/A	SK54-T3	Addition of Component

Being the Applicant for the above mentioned FCC ID : RTQKSCCCBR400A, we hereby confirm that we will apply all of the modifications listed below to the products. These modifications were made to meet the standards of the related FCC Rules & Regulations.

Sincerely,



 Infra Solution Division Leader / Henry Park
 LG CNS Co., Ltd.