

## **Pro-Nets Technology Corporation**

7F, No.95, Lide St., Chung Ho City Taipei 235 Taiwan R.O.C.

FCC ID: RXZ-WP61R2

Dear Sir:

The reason we would like to update the test report on FCC website due to the omission of improper parameter (TX Power "8") was set for the prior testing and this resulted the lower conducted RF power with 802.11g mode. Please check the Picture 1 attached below for details.

Therefore, to get the rated RF power by the manufacturer the proper parameter must be set as "14", and this is used for the re-test data we need to correct and re-submitted to FCC.

Please kindly check this and help to update the test report.


If you have any further questions, please let us know.


Thank you in advance and best regards,

Date: April 17, 2007

Printed name: Alex Chen

Signature:

A handwritten signature in cursive script that reads "Alex Chen".



Picture 1