


Appendix A. Photo of Radiated Emission Test




 The results shown in this test report refer only to the sample(s) tested unless otherwise stated. This test report cannot be reproduced, except in full, without prior written permission of the Company.

 SGS Testing Korea Co., Ltd.
 18-34, Sanbon-dong, Gunpo-si, Gyeonggi-do, Korea, 435-040

 Tel. +82 31 428 5700 / Fax. +82 31 427 2371
 www.electrolab.kr.sgs.com



Appendix B. Photos of Field Strength Test





The results shown in this test report refer only to the sample(s) tested unless otherwise stated. This test report cannot be
reproduced, except in full, without prior written permission of the Company.SGS Testing Korea Co., Ltd.18-34, Sanbon-dong, Gunpo-si, Gyeonggi-do, Korea, 435-040

Tel. +82 31 428 5700 / Fax. +82 31 427 2371



Appendix C. Photos of Conducted Power Line Test





The results shown in this test report refer only to the sample(s) tested unless otherwise stated. This test report cannot be
reproduced, except in full, without prior written permission of the Company.SGS Testing Korea Co., Ltd.18-34, Sanbon-dong, Gunpo-si, Gyeonggi-do, Korea, 435-040

Tel. +82 31 428 5700 / Fax. +82 31 427 2371