

CL6 is mounted to inside of the vehicle and end user can not see the label, so that it is not practicable to display the statement requested by FCC 15.19(a)(3) on CL6. For this reason, this statement is described in a user manual.