

Annex A: Photographs of the Test Set-up

Photo 1: Power Line Conducted Emission Test



Photo 2: Power Line Conducted Emission Test



Test report no.: 1-2034-01-02/10-FP



Photo 3: Radiated Emission

