

Annex A: Photographs of the Test Set-up

Photo 1: Power Line Conducted Emission Test




Photo 2: Radiated Emission



Test report no.: 1-3807/11-01-02



Photo 3: Radiated Emission

