


## **Senao Networks Inc.**

3F, No. 529, Chung Cheng Rd., Hsintien, Taipei, Taiwan, R.O.C.

### **GENERAL DECLARATION LETTER**

The output power was incorrectly programmed during the test for about 0.24 dBm higher than limit (max output power 17.24 dBm, limit 17 dBm). To comply with the part 15.407 rule we have reprogrammed the output power to within the limit (new max. output level 16.9 dBm, limit 17 dBm) and all production units will be locked to no higher than this level by the firmware. Thanks.

Best regards,



Senao Networks Inc.

Jyun-cheng Chen, Ph.D./ Vice President-R&D and CTO

TEL: +886-3-328-9289

FAX: +886-3-396-1112

E-mail: [jc.chen@senao.com](mailto:jc.chen@senao.com)