



Issued: 04/29/2024 Report Number: 105746284BOX-001

#### **Setup Photographs:** 6.5
































# 7.5 Setup Photographs:











# 8.5 Setup Photographs:












## 9.5 Setup Photographs:














Issued: 04/29/2024 Report Number: 105746284BOX-001

#### 10.5 Setup Photographs:



















Non-Specific Radio Report Shell Rev. October 2022 Client: Sargent Manufacturing Company – Model: Aperio IN100 Keypad Page 90 of 172





















Non-Specific Radio Report Shell Rev. October 2022 Client: Sargent Manufacturing Company – Model: Aperio IN100 Keypad Page 95 of 172











Non-Specific Radio Report Shell Rev. October 2022 Client: Sargent Manufacturing Company – Model: Aperio IN100 Keypad Page 97 of 172






### 11.5 Setup Photographs:









Page 161 of 172







