





Report No.: T160919S02 Page <u>2</u> of <u>23</u>









Report No. : T160919S02
Page 3 of 23








Report No. : T160919S02
Page 4 of 23









Report No.: T160919S02 Page <u>6</u> of <u>23</u>

Antenna(TX)















Report No.: T160919S02 Page <u>10</u> of <u>23</u>







Report No. : T160919S02
Page 11 of 23







Report No. : T160919S02 Page 12 of 23






Page <u>13</u> of <u>23</u>







Compliance Certification Services Inc.

Report No.: T160919S02 Page <u>14</u> of <u>23</u>






Report No.: T160919S02 Page <u>15</u> of <u>23</u>









Report No.: T160919S02 Page <u>16</u> of <u>23</u>







Report No.: T160919S02 Page <u>17</u> of <u>23</u>






Report No.: T160919S02 Page <u>18</u> of <u>23</u>





Page 19 of 23






Report No.: T160919S02 Page <u>20</u> of <u>23</u>





Report No.: T160919S02 Page 21 of 23





Report No.: T160919S02 Page <u>22</u> of <u>23</u>



