


Test setup photographs for test report 206548A and 206548B

Photograph 1. Spurious radiated emissions test setup



Photograph 2. AC power line conducted emissions test setup