

Error correction list

IPS Corporation 13-June-2011

Original Test Report No.: EMC10122
 Re-issued Test Report No.:EMC11125

Page	Original	Revise	Reason of change
1	(Date)		Addition
2	030MHz - 1000MHz	30MHz - 1000MHz	Typo error
3	ALV2	ALV2(Slim)	Typo error
4	1.2 Summary of Test Result/Worst Margin		Date correction
4	Tansmitter B	Transmitter B	Typo error
4	Serial No. 002	Serial No. Sample2	Typo error
4	PAN35-%A	PAN35-5A	Typo error
5	NVLAP LAB CODE:----Until:December 31,2010	NVLAP LAB CODE:----Until:December 31,2011	Correction
7	Testing Instrumentation	Test Instrumentation --- Test Date:2011-04-19	Addition, Typo error
8	4.4.1 Detection Mode		Date correction
9	4.4.2 Communication Mode		Date correction
10	(ESIB 40)	(Delete)	Correction
10	Test Instrumentation	Test Instrumentation (Test Date:2011-04-19)	Correction
12	(Revise)	<i>data substituted</i>	Correction
13	(Revise)	<i>data substituted</i>	Correction
17	030MHz - 1000MHz	30MHz - 1000MHz	Typo error