

## Scott McCutchan

---

**From:** Scott McCutchan [scott@celectronics.com]  
**Sent:** Friday, June 26, 2009 10:23 AM  
**To:** 'rey@celectronics.com'  
**Cc:** 'Ruby'  
**Subject:** FCC ID: VEDSTAR1000

Mr. Ramirez:

In order for processing of this certification application (FCC ID: VEDSTAR1000) to continue, the following issue(s) will have to be addressed:

- 1) The user's manual originally submitted contains the required RF hazard warnings for the user. However, in the document recently submitted, "MOJIX Response", it is stated that "no RF exposure warnings will be included in the manual". For this type of transmitter, the warning labels must remain in the manual.
- 2) The block diagrams submitted are not sufficient. As per section 2.1033(b)(5), the block diagram(s) must show the frequencies of all oscillators and indicate the signal path and frequency at each block.

The item(s) indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information within 60 days of the original e-mail date may result in application dismissal and forfeiture of the filing fee. Also, please note that partial responses increase processing time and should not be submitted. Please upload responses and/or exhibits to the electronic filing website. Your correspondence number is VEDSTAR1000.

Best regards,

Scott McCutchan  
Operations Manager  
Compatible Electronics TCB