


August 12, 2010

**Request for RF Register change – WMCU Firmware Version TP6 to TP7
(2010 Wireless DJ Turntable Controller – XBOX 360)**


Please be notified that we, the undersigned, Activision declare that the reasons for this RF Register change - WMCU Firmware Version TP6 to TP7 are as below:

VCO stability improvement is made by turning on driver stage prior to PA turn on by 2.5us. Previously some frequency offset failures on production line were encountered due to open loop modulation format. Change compliance impact NIL was verified by band-edge analysis (see below).

TP7




TP6





444 Castro Street • Suite 140
Mountain View, Ca. 94041

Upper band-edge Pre-change (YELLOW) and Post-change (BLUE)



Sincerely,

Stephen N. Withers
Product Manager
RedOctane, Inc
Phone: 650.930.1243
Fax: 650.930.1108
E-mail: swithers@redoctane.com

