



American Telecommunications Certification Body Inc  
6731 Whittier Ave, McLean, VA 22101

May 13, 2009

RE: Asian Express Holding Ltd

FCC: VLE15052-PPL-B

ATCB007609

I have a few comments on this Application. Depending on your responses, kindly understand there may be additional comments.

1. Comparison of Internal photographs and schematics do not match. The number of switches, and external wired switches do not match. It appears the incorrect schematic was provided. The schematic provided shows a charging circuit that is also not relevant.

Answer: Yes, we sent the wrong sch before. Uploaded the right sch and operational description.

2. Users manual shows different controller, with different number of buttons and shape. Manual does not appear to match product.

Answer: Revised and uploaded.

3. Authorization letter states the incorrect FCCID. Please revise it.

Answer: deleted the FCC ID from the letter.

4. The external photo and the photo in label appear 49MHz, That is not match with the other document, Please correct.

Answer: resent the correct one.

5. Internal photographs show both 27 and 49 MHz information/versions. Please review. Device must match as certified.

Answer: delete the 49MHz internal photo which is not belong to this device.

6. User manual must show where 15.21 statement is found. Please review.

Answer: all pages were put on the box of the device.

8. FYI...Test report described the power supply with 9.0V(1\*9.0V "6F22" Size Battery), But user manual showed the power supply with 2 X 1.5V "AA" battery.

Answer: refer to 2. the power supply is consistent with the report.