


Test Report #: EMC\_JUNIP-042-22001\_FCC\_22\_24\_27\_90

Page 89 of 162




#### UMTS II




### Test Report #: EMC\_JUNIP-042-22001\_FCC\_22\_24\_27\_90






Page 90 of 162








Page 92 of 162



#### UMTS IV




### Test Report #: EMC\_JUNIP-042-22001\_FCC\_22\_24\_27\_90






Page 93 of 162


























Page 98 of 162






## Test Report #: EMC\_JUNIP-042-22001\_FCC\_22\_24\_27\_90 Date of Report 2022-05-17 Page 99 of 162











Page 101 of 162






# Test Report #: EMC\_JUNIP-042-22001\_FCC\_22\_24\_27\_90 Date of Report 2022-05-17 Page 102 of 162













Page 104 of 162
















Page 107 of 162






# Test Report #: EMC\_JUNIP-042-22001\_FCC\_22\_24\_27\_90 Date of Report 2022-05-17 Page 108 of 162














Page 110 of 162
















Page 113 of 162













Page 116 of 162






## Test Report #: EMC\_JUNIP-042-22001\_FCC\_22\_24\_27\_90 Date of Report 2022-05-17 Page 117 of 162













Page 119 of 162






# Test Report #: EMC\_JUNIP-042-22001\_FCC\_22\_24\_27\_90 Date of Report 2022-05-17 Page 120 of 162












Page 122 of 162



# Test Report #: EMC\_JUNIP-042-22001\_FCC\_22\_24\_27\_90 Date of Report 2022-05-17 Page 123 of 162



