From:SS [ssliou@etc.org.tw]Sent:Wednesday, December 10, 2008 3:51 AMTo:Lucy Tsai; cindy628Subject:Re: Loopcomm Technology, Inc., FCC ID: VYTLP-8186, Assessment NO.: AN08T8480,
Notice#1

Dear Lucy,

The PCB antenna trace you have mentioned was disconnected to the RF circuit so it has no function. An external antenna was employed only.

Best regards,

S. S. Liou
Section Manager
EMC Testing Dept. II
Electronics Testing Center, Taiwan
Tel: +886-2-26023052 ext. 20
Email: ssliou@etc.org.tw
URL: <u>http://www.etc.org.tw</u>

--

Hi SS,

Please address following issues. Q#1: Except a external dipole antenna, a printed antenna is shown on the PCB board but there has no information addressed it in this application. Please explain.

Best Regards,

Lucy Tsai CCS

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information within 30 days of the original e-mail date may result in application dismissal and forfeiture of the filing fee. Also, please note that partial responses increase processing time and should not be submitted Any questions about the content of this correspondence should be directed to the e-mail address listed below the name of the sender.