


Prüfbericht - Nr.:
Test Report No.

16016886 001

Seite 1 von 16
Page 1 of 16




down 3dB

Date: 3.APR.2009 06:25:33

Prüfbericht - Nr.:
Test Report No.

16016886 001

Seite 2 von 16
Page 2 of 16




down 3dB

Date: 3.APR.2009 06:20:58

Prüfbericht - Nr.:
Test Report No.

16016886 001

Seite 3 von 16
Page 3 of 16




down 3dB

Date: 3.APR.2009 06:17:43

Prüfbericht - Nr.:
Test Report No.

16016886 001

Seite 4 von 16
Page 4 of 16




down 3dB

Date: 3.APR.2009 04:19:24

Prüfbericht - Nr.:
Test Report No.

16016886 001

Seite 5 von 16
Page 5 of 16




down 3dB

Date: 3.APR.2009 04:23:19

Prüfbericht - Nr.:
Test Report No.

16016886 001

Seite 6 von 16
Page 6 of 16




down 3dB

Date: 3.APR.2009 04:25:41

Prüfbericht - Nr.:
Test Report No.

16016886 001

Seite 7 von 16
Page 7 of 16




down 3dB

Date: 3.APR.2009 03:58:51

Prüfbericht - Nr.:
Test Report No.

16016886 001

Seite 8 von 16
Page 8 of 16




down 3dB

Date: 3.APR.2009 04:08:29

Prüfbericht - Nr.:
Test Report No.

16016886 001

Seite 9 von 16
Page 9 of 16




down 3dB

Date: 3.APR.2009 06:02:23

Prüfbericht - Nr.:
Test Report No.

16016886 001

Seite 10 von 16
Page 10 of 16




down 3dB

Date: 3.APR.2009 06:07:00

Prüfbericht - Nr.:
Test Report No.

16016886 001

Seite 11 von 16
Page 11 of 16



down 3dB

Date: 3.APR.2009 06:09:01

