



APPENDIX 1: Photographs of test setup

Radiated Emission
Front




Rear



ECU Worst Case Position (X-axis)


X-axis



Y-axis




Z-axis




Antenna Worst Case Position (X-axis)

Antenna A


X-axis



Y-axis



Z-axis



UL Japan, Inc.

Head Office EMC Lab.


4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8116


Facsimile : +81 596 24 8124

Antenna Worst Case Position (Z-axis)
Antenna B


X-axis



Y-axis




Z-axis




Antenna Worst Case Position (X-axis)
Antenna C


X-axis



Y-axis




Z-axis




Antenna Worst Case Position (Z-axis)
Antenna D


X-axis



Y-axis




Z-axis




Antenna Worst Case Position (Z-axis)
Antenna E


X-axis



Y-axis




Z-axis




Antenna Worst Case Position (Z-axis)
Antenna F


X-axis



Y-axis




Z-axis




Antenna Worst Case Position (Z-axis)
Antenna G

X-axis



Y-axis



Z-axis

