









**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2021-00840  
 Page (41) / (250) Pages



**ANT2\_802.11n\_HT20\_UNII 1**






**ANT2\_802.11n\_HT20\_UNII 2A**






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2021-00840  
 Page (42) / (250) Pages



**ANT2\_802.11n\_HT20\_UNI1 2C**






**ANT2\_802.11n\_HT20\_UNI1 3**






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2021-00840  
 Page (43) / (250) Pages



**ANT3\_802.11n\_HT20\_UNII 1**






**ANT3\_802.11n\_HT20\_UNII 2A**






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2021-00840  
 Page (44) / (250) Pages



**ANT3\_802.11n\_HT20\_UNII 2C**






**ANT3\_802.11n\_HT20\_UNII 3**






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2021-00840  
 Page (45) / (250) Pages



**ANT4\_802.11n\_HT20\_UNII 1**






**ANT4\_802.11n\_HT20\_UNII 2A**






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2021-00840  
 Page (46) / (250) Pages



**ANT4\_802.11n\_HT20\_UNII 2C**






**ANT4\_802.11n\_HT20\_UNII 3**






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2021-00840  
 Page (47) / (250) Pages



**ANT1\_802.11ac\_VHT20\_UNII 1**






**ANT1\_802.11ac\_VHT20\_UNII 2A**






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2021-00840  
 Page (48) / (250) Pages



**ANT1\_802.11ac\_VHT20\_UNII 2C**






**ANT1\_802.11ac\_VHT20\_UNII 3**








**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2021-00840  
 Page (49) / (250) Pages



ANT2\_802.11ac\_VHT20\_UNII 1






ANT2\_802.11ac\_VHT20\_UNII 2A






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2021-00840  
 Page (50) / (250) Pages



ANT2\_802.11ac\_VHT20\_UNII 2C






ANT2\_802.11ac\_VHT20\_UNII 3






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2021-00840  
 Page (51) / (250) Pages



**ANT3\_802.11ac\_VHT20\_UNII 1**






**ANT3\_802.11ac\_VHT20\_UNII 2A**






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2021-00840  
 Page (52) / (250) Pages



**ANT3\_802.11ac\_VHT20\_UNII 2C**






**ANT3\_802.11ac\_VHT20\_UNII 3**






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2021-00840  
 Page (53) / (250) Pages



**ANT4\_802.11ac\_VHT20\_UNII 1**






**ANT4\_802.11ac\_VHT20\_UNII 2A**






**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2021-00840  
 Page (54) / (250) Pages



**ANT4\_802.11ac\_VHT20\_UNI1 2C**





**ANT4\_802.11ac\_VHT20\_UNI1 3**





**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501




Report No.:  
 CTK-2021-00840  
 Page (55) / (250) Pages



**ANT1\_802.11n\_HT40\_UNI 1**



**ANT1\_802.11n\_HT40\_UNI 2A**





**ANT1\_802.11n\_HT40\_UNI 2C**



**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2021-00840  
 Page (56) / (250) Pages





ANT1\_802.11n\_HT40\_UNII 3







**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501




Report No.:  
 CTK-2021-00840  
 Page (57) / (250) Pages



**ANT2\_802.11n\_HT40\_UNI I 1**



**ANT2\_802.11n\_HT40\_UNI I 2A**





**ANT2\_802.11n\_HT40\_UNI I 2C**



**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2021-00840  
 Page (58) / (250) Pages





ANT2\_802.11n\_HT40\_UNI1 3





**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501




Report No.:  
 CTK-2021-00840  
 Page (59) / (250) Pages



**ANT3\_802.11n\_HT40\_UNI I 1**



**ANT3\_802.11n\_HT40\_UNI I 2A**





**ANT3\_802.11n\_HT40\_UNI I 2C**



**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2021-00840  
 Page (60) / (250) Pages





**ANT3\_802.11n\_HT40\_UNII 3**





**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501




Report No.:  
 CTK-2021-00840  
 Page (61) / (250) Pages



**ANT4\_802.11n\_HT40\_UNI I 1**



**ANT4\_802.11n\_HT40\_UNI I 2A**





**ANT4\_802.11n\_HT40\_UNI I 2C**



**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501

Report No.:  
 CTK-2021-00840  
 Page (62) / (250) Pages





ANT4\_802.11n\_HT40\_UNI1 3





**CTK Co., Ltd.**  
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,  
 Yongin-si, Gyeonggi-do, Korea  
 Tel: +82-31-339-9970  
 Fax: +82-31-624-9501




Report No.:  
 CTK-2021-00840  
 Page (63) / (250) Pages



**ANT1\_802.11ac\_VHT40\_UNI1**



**ANT1\_802.11ac\_VHT40\_UNI1 2A**



**ANT1\_802.11ac\_VHT40\_UNI1 2C**