








CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2022-03105
 Page (125) / (281) Pages



ANT1_802.11ax_HE20_26T_UNII 1





ANT1_802.11ax_HE20_26T_UNII 2A





CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501




Report No.:
 CTK-2022-03105
 Page (126) / (281) Pages






ANT1_802.11ax_HE20_26T_UNII 2C



ANT1_802.11ax_HE20_26T_UNII 3



ANT2_802.11ax_HE20_26T_UNII 1







ANT2_802.11ax_HE20_26T_UNII 2A






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2022-03105
 Page (128) / (281) Pages



ANT2_802.11ax_HE20_26T_UNII 2C






ANT2_802.11ax_HE20_26T_UNII 3






CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2022-03105
 Page (129) / (281) Pages



ANT1_802.11ax_HE20_242T_UNII 1







ANT1_802.11ax_HE20_242T_UNII 2A





CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501


Report No.:
 CTK-2022-03105
 Page (130) / (281) Pages






ANT1_802.11ax_HE20_242T_UNII 2C






ANT1_802.11ax_HE20_242T_UNII 3












ANT2_802.11ax_HE20_242T_UNII 1



ANT2_802.11ax_HE20_242T_UNII 2A



ANT2_802.11ax_HE20_242T_UNII 2C





ANT2_802.11ax_HE20_242T_UNII 3





CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501





Report No.:
 CTK-2022-03105
 Page (133) / (281) Pages



ANT1_802.11n_HT40_UNII 1



ANT1_802.11n_HT40_UNII 2A





ANT1_802.11n_HT40_UNII 2C





CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501



Report No.:
 CTK-2022-03105
 Page (134) / (281) Pages







ANT1_802.11n_HT40_UNII 3



ANT2_802.11n_HT40_UNII 1



ANT2_802.11n_HT40_UNII 2A





ANT2_802.11n_HT40_UNII 2C





CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501



Report No.:
 CTK-2022-03105
 Page (136) / (281) Pages







ANT2_802.11n_HT40_UNII 3



ANT1_802.11ac_VHT40_UNII 1



ANT1_802.11ac_VHT40_UNII 2A





ANT1_802.11ac_VHT40_UNII 2C





CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501



Report No.:
 CTK-2022-03105
 Page (138) / (281) Pages







ANT1_802.11ac_VHT40_UNII 3



ANT2_802.11ac_VHT40_UNII 1



ANT2_802.11ac_VHT40_UNII 2A





ANT2_802.11ac_VHT40_UNII 2C



CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501

Report No.:
 CTK-2022-03105
 Page (140) / (281) Pages





ANT2_802.11ac_VHT40_UNII 3





CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501





Report No.:
 CTK-2022-03105
 Page (141) / (281) Pages



ANT1_802.11ax_HE40_26T_UNII 1



ANT1_802.11ax_HE40_26T_UNII 2A





ANT1_802.11ax_HE40_26T_UNII 2C





CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501



Report No.:
 CTK-2022-03105
 Page (142) / (281) Pages







ANT1_802.11ax_HE40_26T_UNII 3



ANT2_802.11ax_HE40_26T_UNII 1



ANT2_802.11ax_HE40_26T_UNII 2A





ANT2_802.11ax_HE40_26T_UNII 2C





CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501



Report No.:
 CTK-2022-03105
 Page (144) / (281) Pages







ANT2_802.11ax_HE40_26T_UNII 3



ANT1_802.11ax_HE40_484T_UNII 1



ANT1_802.11ax_HE40_484T_UNII 2A





ANT1_802.11ax_HE40_484T_UNII 2C





CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501



Report No.:
 CTK-2022-03105
 Page (146) / (281) Pages







ANT1_802.11ax_HE40_484T_UNII 3



ANT2_802.11ax_HE40_484T_UNII 1



ANT2_802.11ax_HE40_484T_UNII 2A





ANT2_802.11ax_HE40_484T_UNII 2C




CTK Co., Ltd.
 (Ho-dong), 113, Yejik-ro, Cheoin-gu,
 Yongin-si, Gyeonggi-do, Korea
 Tel: +82-31-339-9970
 Fax: +82-31-624-9501


Report No.:
 CTK-2022-03105
 Page (148) / (281) Pages





ANT2_802.11ax_HE40_484T_UNII 3





ANT1_802.11ac_VHT80_UNII 1



ANT1_802.11ac_VHT80_UNII 2A




ANT1_802.11ac_VHT80_UNII 2C




ANT1_802.11ac_VHT80_UNII 2C



ANT1_802.11ac_VHT80_UNII 3




ANT2_802.11ac_VHT80_UNII 1




ANT2_802.11ac_VHT80_UNII 2A




ANT2_802.11ac_VHT80_UNII 2C




ANT2_802.11ac_VHT80_UNII 2C





ANT2_802.11ac_VHT80_UNII 3





ANT1_802.11ax_HE80_26T_UNII 1



ANT1_802.11ax_HE80_26T_UNII 2A




ANT1_802.11ax_HE80_26T_UNII 2C




ANT1_802.11ax_HE80_26T_UNII 2C



ANT1_802.11ax_HE80_26T_UNII 3





ANT2_802.11ax_HE80_26T_UNII 1



ANT2_802.11ax_HE80_26T_UNII 2A



ANT2_802.11ax_HE80_26T_UNII 2C



ANT2_802.11ax_HE80_26T_UNII 2C

ANT2_802.11ax_HE80_26T_UNII 3