

Sharon Hoffman

From: B.PELLERIN [b.pellerin@emitech.fr]
Sent: Thursday, June 11, 2009 10:51 AM
To: 'TEI Email'
Subject: RE:job 1132FC9Probonholdemail 2.doc

Hello,

Here are response to your question:

1)I sent you a photograph of variation without driver and USB port on web site.

2) The version tested on the report is the version with USB port and his driver. For the version without USB, the electronic card is the same but the usb plug and USB driver component are not install. For the test, the version tested were usb plug because it's a more completely products.

Sincerely

Bruno PELLERIN

Responsable Entité Technique Radio



Z.A. de l'Observatoire – 3, rue des coudriers – 78180 Montigny-Le-Bretonneux

T 01 30 57 55 55 – F 01 30 57 86 32 – E-mail b.pellerin@emitech.fr – Web : www.emitech.fr



Pensez Environnement, imprimez seulement si nécessaire.



Think Environment, print only if necessary

De : TEI Email [mailto:TEI@timcoengr.com]

Envoyé : mardi 9 juin 2009 15:24

À : b.pellerin@emitech.fr

Objet : 1132FC9Probonholdemail 2.doc

TIMCO ENGINEERING INC.

849 NW State Road 45

Newberry, Florida 32669

<http://www.timcoengr.com>

888.472.2424 F 352.472.2030 email: tei@timcoengr.com

TCB & FCB

FCC Approvals

Industry Canada Approvals

Notified Body for Europe

6/9/2009

MR. BRUNO PELLERIN

EMITECH ILE DE FRANCE

+33 (0) 1 55 19 57 00 +33 (0) 1 30 57 87 82

b.pellerin@emitech.fr

SUBJECT: TIMCO-TCB/Request for additional info - ENERSYS DELAWARE INC - FCC ID: WT549514B6579

REFERENCE: JOB 1132FC9

Dear MR. PELLERIN:

This application is on hold until these questions are resolved. Please answer all question(s) together and only respond to tei@timcoengr.com. Any other method will cause **unnecessary delay**.

DO NOT HIT REPLY! Your response should be sent **ONLY** to tei@timcoengr.com. Any additional exhibits that are sent should be **UPLOADED** at our web site – please do not attach files to your email. Responses should also contain the job number, applicant name and FCC ID of the device. If an acceptable response is not received within 2 weeks the job will be closed & there will be additional charges to reopen.

ANSWER ALL QUESTIONS. Be sure to number or identify your answer with the corresponding question. If you are referring to another document, be sure to give the page number and paragraph reference where your response can be found.

Thank you for your response regarding the label locations. Based on your response:

1. Photographs should be provided for both variations. Please provide photographs of the variation without the driver and USB port.
2. Please provide a statement that there are 2 models and that both models were tested and the data shown in the report represents the worst case.

Sincerely,

Timco Engineering, Inc.

No virus found in this incoming message.

Checked by AVG - www.avg.com

Version: 8.5.339 / Virus Database: 270.12.50/2150 - Release Date: 06/11/09 05:53:00