
DEKRA Certification, Inc. 405 Glenn Dr. Suite 12, Sterling, VA 20164 United States of America



## Appendix B: Photographs

**Report No**: 3825ERM.003 10-04-2022












Figure B4. Front view of the Conducted DUT





Figure B5. Rear view of the Conducted DUT



Figure B6. View of the Conducted DUT with accessories





Figure B7. Radiated Setup 1



Figure B8. Radiated Setup 2