Test report no.: 1-2387-01-03/10-A



Annex A Photographs of the test setup

Photo documentation

Photo 1: AC Line conducted



2010-10-04 Page 63 of 73


Test report no.: 1-2387-01-03/10-A



Photo 2: Radiated spurious emissions



Photo 3: Radiated spurious emissions



2010-10-04 Page 64 of 73