

Appendix 3

Prüfbericht - **Nr.:**
Test Report No.

19660240 001, 19660241 001 19660242 001
19660243 001, 19660244 001, 19660245 001
19660246 001

Seite 1 von 5
Page 1 of 5



Back panel removed



Back cover


Appendix 3

Prüfbericht - Nr.:

19660240 001, 19660241 001 19660242 001
19660243 001, 19660244 001, 19660245 001
19660246 001

Test Report No.

Seite 2 von 5
Page 2 of 5



Outside Panel removed




Outside panel removed


Prüfbericht - Nr.:

19660240 001, 19660241 001 19660242 001
19660243 001, 19660244 001, 19660245 001
19660246 001Seite 3 von 5
Page 3 of 5

Test Report No.



Internal PCB Top view




Internal PCB Rear View


Prüfbericht - **Nr.:**
Test Report No.

19660240 001, 19660241 001 19660242 001
19660243 001, 19660244 001, 19660245 001
19660246 001

Seite 4 von 5
Page 4 of 5



Internal PCB view



Internal PCB View

Appendix 3

Prüfbericht - Nr.: 19660240 001, 19660241 001 19660242 001
 Test Report No. 19660243 001, 19660244 001, 19660245 001
 19660246 001

Seite 5 von 5
 Page 5 of 5



Antenna Location Image