
Statement

Because there is no component in position R31, So R31 disconnect, therefore there is

no transmitter from antenna port



antenna

intenna ANT 2 can transmit

Albert Mirao

Signature:

Title: Hardware Engineer

Date: 2016-4-12

Seeed Technology Co., Ltd.