

SES-MOD-20070419-99490, E020075  
From: Center, Ronald E  
[Ronald.E.Center@boeing.com]  
Sent: Monday, April 23, 2007 4:33 PM  
To: Towanda Bryant  
Cc: Douglass, Bob  
Subject: RE: SES-MOD-20070419-99490, E020075

Towanda,

I have reviewed the FAX and believe that I have discovered my error. By placing a zero after the "K", I inadvertently added an extra digit on the following emission designators. It appears that the system did not recognize them, and therefore rejected the input. I believe that all other technical data associated with these emissions is correct.

I am not sure of the best method of correction, but here are the changes. I have listed the original submission, followed by the corrected emission designator.

Original Emission	Submission	Revised Emission	Submission
307K0G7D		307KG7D	
461K0G7D		461KG7D	
512K0G7D		512KG7D	
154K0G7D		154KG7D	
615K0G7D		615KG7D	
922K0G7D		922KG7D	

Please let me know if this answers your questions.

Thanks,

Ron Center  
The Boeing Company  
Enterprise Frequency Management Services  
Seattle, WA  
(206) 544-6583

---

From: Douglass, Bob  
Sent: Monday, April 23, 2007 1:01 PM  
To: Center, Ronald E  
Subject: FW: SES-MOD-20070419-99490, E020075

Ron. Towanda is sending a sheet to use for changes. At this point I don't know any more then they are emission problems.

Bob

---

From: Towanda Bryant [mailto:Towanda.Bryant@fcc.gov]  
Sent: Monday, April 23, 2007 12:55 PM

To: Douglass, Bob  
Subject: SES-MOD-20070419-99490, E020075

Hello!!!

I am faxing you an autogrant check sheet that has flagged 6 of your emissions, please have an engineer review and fix and email me the changes ASAP!!!! Please have them contact Trang on 202-418-2734 if they need help with the emissions.

Tnx. T.

\*\*\* Non-Public: For Internal Use Only \*\*\*