

From: [Barry Persh](#)
To: [Jae Lim](#)
Subject: RE: SES-REG-20180906-04468; Call Sign: E190810
Date: Tuesday, October 22, 2019 12:15:51 PM
Attachments: [image001.png](#)

The applicant's engineer indicates that the letter "O" was mistakenly placed where the number "0" should be, and that the correct emission designator is:

2M00G7W

Hopefully that resolves any issue with the application, but please let us know if you need anything else on this.

Thank you.

Barry S. Persh | Gray Miller Persh LLP

2233 Wisconsin Avenue NW, Suite 226

Washington, DC 20007

(202) 776-2458

bpersh@graymillerpersh.com

This message from the law firm of Gray Miller Persh LLP may contain confidential or privileged information. If you received this transmission in error, please contact us immediately by telephone or email. Disclosure or use of any part of this message by persons other than the intended recipient is prohibited.

From: Barry Persh
Sent: Wednesday, October 16, 2019 10:02 AM
To: Jae Lim <Jae.Lim@fcc.gov>
Subject: RE: SES-REG-20180906-04468; Call Sign: E190810

Thanks, we are checking with the applicant's engineer on this.

Barry S. Persh | Gray Miller Persh LLP

2233 Wisconsin Avenue NW, Suite 226

Washington, DC 20007

(202) 776-2458

bpersh@graymillerpersh.com


This message from the law firm of Gray Miller Persh LLP may contain confidential or privileged information. If you received this transmission in error, please contact us immediately by telephone or email. Disclosure or use of any part of this message by persons other than the intended recipient is prohibited.

From: Jae Lim <Jae.Lim@fcc.gov>
Sent: Tuesday, October 15, 2019 12:27 PM
To: Barry Persh <bpersh@graymillerpersh.com>
Subject: SES-REG-20180906-04468; Call Sign: E190810

Hi Barry Persh,

Your Emission Designator information is incorrect.

Please verify Emission.



Jae Lim
FCC/IB
1-202-418-2899