



Daniel C.H. Mah
Regulatory Counsel
(202) 478-7137

March 1, 2012

VIA IBFS

Paul Blais
Chief, Systems Analysis Branch
Satellite Division, International Bureau
445 12th Street SW
Washington, DC 20554

Dear Mr. Blais,

**Re: Erratum – SES Americom, Inc.
File No. SES-STA-20120229-00225**

SES Americom, Inc. (“SES”) hereby corrects a transcription error in the Narrative to the above-referenced application. Specifically, the maximum EIRP for the Telemetry 4 frequency specified in the narrative should be 9.0 dBW instead of 8.0 dBW. This correction does not change the technical analysis in the application. The corrected EIRP value is still well below the allowed EIRP and the power flux density limits discussed in the Narrative.

Please contact the undersigned if you have any questions.

Yours sincerely,

/s/
Daniel C.H. Mah
Regulatory Counsel
SES Americom, Inc.