
LASER LIGHT
DO NOT STARE INTO BEAM
CAUTION
Replace the battery within 3 minutes.
Failure to do so may result in loss of data.
Periodical cleaning is required. If USB terminals become dirty, communication errors may occur.
US LISTED
AUGUST, 2004
00001 01A, KA


LASER LIGHT
DO NOT STARE INTO BEAM
CAUTION
Replace the battery within 3 minutes.
Failure to do so may result in loss of data.
Periodical cleaning is required. If USB terminals become dirty, communication errors may occur.
US LISTED


FHT401S3W :K0030034-A006
DC 3.6V 3.0A
4-1-1 KAMIODANAKA NAKAHARA
KAWASAKI KANAGAWA JAPAN
211-8588
MADE IN JAPAN FUJITSU LIMITED


FUJITSU