
7435A823 QAPE ES
INTEL©©'03
Dothan 533 FSB
1.86
GHz
940120A01


940120A01


7437A933 QAPF ES
INTEL©'03
Dothan 533 FSB
2.0
GHz
940120A01


940120A01


7441A184 QDRB ES
INTEL©'03
940120A01


940120A01

MDOAD4G3I448041C0H
DDR333(2.5) 1GX16
S/N: 452XR (ADFDB1A1607H)
Warranty void if removed
ADD9608A8C-6B
940120A01


ADD9608A8C-6B
940120A01

MDOAD4F4H3450B1C0H
DDR333(2.5) 512MX8
S/N: 442TH (ADFDB290800H)
Warranty void if removed
94V-0
940120A01


A-Data
940120A01

MDOAD4F3G3460D1C02
DDR 333(2.5) 256MX8
S/N:451TH (ADFDB1808012)
Warranty void if removed
DATA
20451
ADD8608A8A-6B
940120A01

SY4521000037
P/N:18-060005-N0
1140L1017462
DATA
20451
ADD8608A8A-6B
940120A01

MDOHY4F3G3460D1C0Z
DDR333(2.5) 256MX8
S/N: 447TR (HYFDB180801Z)
Warranty void if removed
hynix 442AP
HY5DU56822BT-J
KOR
94V-0
940120A01

R-DATA
SY4521000048
P/N:18-060005-V0
1140L1017473
hynix 442AP
HY5DU56822BT-J
KOR
SO200RCB
940120A01

TwinMOS®
P/N:M2S5I08D6APS5F081AA-T
MODEL NO:M2S5I08D-PS
S/N: 431M45M49422316
PC2700(CL2.5) 256MB DDR SO-DIMM
Warranty Void If Removed
940120A01


A2S56D30BTP
425ALM22
TAIWAN -6
940120A01

FUJITSU
MADE IN THAILAND
940120A01


940120A01

FUJITSU
MADE IN THAILAND
60.0GB
DEVICE0
DEVICE1
CABLE SEL
940120A01


940120A01

FUJITSU
MADE IN THAILAND
MODEL NO MHT2080AT
PART NO CA06297-B278000TW
SER NO NN9P7A1.3A01 DATE 2004-10
RATING +5V⎓0.55A
REV NO A
LBA:156301488
80.0GB
DEVICE0
DEVICE1
JUMPER
CABLE SEL
PIN1
940120A01

Fujitsu
MADE IN THAILAND
UGA311
30TCC
CA13135-B7
T8421JG
940120A01

DISK DRIVE MK6025GAS
HDD2189 C ZE01 T
S/N 842505861 4S9 EC A
TOSHIBA CORPORATION
MADE IN PHILIPPINES
CAUTION
DO NOT DISASSEMBLE OR MODIFY.
DO NOT REMOVE ANY LABELS.
DO NOT PUSH ON THE TOP COVER.
HANDLE ONLY BY SIDES OF BASE.
AVOID GIVING SHOCK.
DO NOT COVER BREATHING HOLE.
RATTLE NOISE IS NORMAL.
940120A01

TOSHIBA
VOID WARRANTY IF SEAL BROKEN
940120A01

940120A01


940120A01

940120A01

940120A01

CD-R/RW/DVD-ROM DRIVE
940120A01


940120A01