
WARNING – Certain internal parts are intentionally not grounded and may present a risk of electric shock only during servicing. Service Personnel – Do not contact the following parts while the appliance is energized : Low voltage transformer frame.
WARNING – FOR CONTINUED PROTECTION AGAINST EXCESSIVE RADIATION REPLACE ONLY WITH:
PRIMARY INTERLOCK SWITCH MFGRD BY STARON H-Z ELECTRONICS CO. LTD SZM-V16-FA-4G 16A 125, 250V AC SECONDARY INTERLOCK SWITCH MFGRD BY STARON H-Z ELECTRONICS CO. LTD SZM-V16-FA-6G 16A 125, 250V AC MONITOR SWITCH MFGRD BY STARON H-Z ELECTRONICS CO. LTD SZM-V16-FA-6G
WARNING – For continued protection against radiation hazard, replace only with miscellaneous type 314015 15A or MDA 15A fuse.
WHEN REPLACING FUSE CHECK OPERATION OF DOOR INTERLOCK AND INTERLOCK MONITOR CIRCUIT AND REPLACE ANY FAULTY COMPONENT
MFO-2115E