Internal photo





This report shall not be reproduced except in full, without the written approval of TA Technology (Shanghai) Co., Ltd.





This report shall not be reproduced except in full, without the written approval of TA Technology (Shanghai) Co., Ltd.





This report shall not be reproduced except in full, without the written approval of TA Technology (Shanghai) Co., Ltd.





This report shall not be reproduced except in full, without the written approval of TA Technology (Shanghai) Co., Ltd.





ID72-818; ID72-818D

This report shall not be reproduced except in full, without the written approval of TA Technology (Shanghai) Co., Ltd.





ID72-810; ID72-810D

This report shall not be reproduced except in full, without the written approval of TA Technology (Shanghai) Co., Ltd.





ID72-018; ID72-018D

This report shall not be reproduced except in full, without the written approval of TA Technology (Shanghai) Co., Ltd.





ID72-010; ID72-010D

This report shall not be reproduced except in full, without the written approval of TA Technology (Shanghai) Co., Ltd.





This report shall not be reproduced except in full, without the written approval of TA Technology (Shanghai) Co., Ltd.



This report shall not be reproduced except in full, without the written approval of TA Technology (Shanghai) Co., Ltd.





This report shall not be reproduced except in full, without the written approval of TA Technology (Shanghai) Co., Ltd.



This report shall not be reproduced except in full, without the written approval of TA Technology (Shanghai) Co., Ltd.