John Kennedy

From: Heidt, Robert [rheidt@harris.com]
Sent: Tuesday, February 06, 2007 10:42 AM
To: John Kennedy
Subject: RE: FCC File # 0900-EX-ST-2006

John

Correct Lat Lon of Melbourne Florida Lat 28 05 01 North long 80 36 29 West

No aircraft are involved in the testing.

Radios will be both Vehicular mount and man portable ML & MLP

Thanks

Robert Heidt
Senior Principal Engineer
Advanced Development Group
Harris Corporation
(585)242-3767

From: John Kennedy [mailto:John.Kennedy@fcc.gov]
Sent: Tuesday, February 06, 2007 10:10 AM
To: Heidt, Robert
Subject: FCC File # 0900-EX-ST-2006

Mr. Robert Heidt,

It has been pointed out that the longitude in application 0900-EX-ST-2006 is in error. The longitude listed would put the operations near the Azore Island of Portugal. Also, are there aircraft involved in this assignment? Station class for mobiles (vehicular mounted) is ML, and for portables it's MLP.

John W. Kennedy
Federal Communications Commission
Experimental Licensing Branch
(202) 418-2484