12.2.2. Test Graphs



11AX20MIMO_Ant1_5955



11AX20MIMO_Ant2_5955



11AX20MIMO_Ant1_6175

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX20MIMO_Ant2_6175



11AX20MIMO_Ant1_6415



11AX20MIMO_Ant2_6415

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX20MIMO_Ant1_6435



11AX20MIMO_Ant2_6435



11AX20MIMO_Ant1_6475

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX20MIMO_Ant2_6475



11AX20MIMO_Ant1_6515



11AX20MIMO_Ant2_6515

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX20MIMO_Ant1_6535



11AX20MIMO_Ant2_6535



11AX20MIMO_Ant1_6715

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX20MIMO_Ant2_6715



11AX20MIMO_Ant1_6855



11AX20MIMO_Ant2_6855

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX20MIMO_Ant1_6875



11AX20MIMO_Ant2_6875



11AX20MIMO_Ant1_7015

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX20MIMO_Ant2_7015



11AX20MIMO_Ant1_7115



11AX20MIMO_Ant2_7115

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX40MIMO_Ant1_5965



11AX40MIMO_Ant2_5965



11AX40MIMO_Ant1_6165

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX40MIMO_Ant2_6165



11AX40MIMO_Ant1_6405



11AX40MIMO_Ant2_6405

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX40MIMO_Ant1_6445



11AX40MIMO_Ant2_6445



11AX40MIMO_Ant1_6485

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX40MIMO_Ant2_6485



11AX40MIMO_Ant1_6525



11AX40MIMO_Ant2_6525

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX40MIMO_Ant1_6565



11AX40MIMO_Ant2_6565



11AX40MIMO_Ant1_6725

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX40MIMO_Ant2_6725



11AX40MIMO_Ant1_6845



11AX40MIMO_Ant2_6845

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX40MIMO_Ant1_6885



11AX40MIMO_Ant2_6885



11AX40MIMO_Ant1_7005

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX40MIMO_Ant2_7005



11AX40MIMO_Ant1_7085



11AX40MIMO_Ant2_7085

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX80MIMO_Ant1_5985



11AX80MIMO_Ant2_5985



11AX80MIMO_Ant1_6145

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX80MIMO_Ant2_6145



11AX80MIMO_Ant1_6385



11AX80MIMO_Ant2_6385

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX80MIMO_Ant1_6465



11AX80MIMO_Ant2_6465



11AX80MIMO_Ant1_6545

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX80MIMO_Ant2_6545



11AX80MIMO_Ant1_6625



11AX80MIMO_Ant2_6625

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX80MIMO_Ant1_6705



11AX80MIMO_Ant2_6705



11AX80MIMO_Ant1_6785

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX80MIMO_Ant2_6785



11AX80MIMO_Ant1_6865



11AX80MIMO_Ant2_6865

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX80MIMO_Ant1_6945



11AX80MIMO_Ant2_6945



11AX80MIMO_Ant1_7025

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.



11AX80MIMO_Ant2_7025

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

12.3. Appendix B: Duty Cycle

12.3.1. Test Result

Mode	On Time (msec)	Period (msec)	Duty Cycle x (Linear)	Duty Cycle (%)	Duty Cycle Correction Factor (dB)	1/T Minimum VBW (kHz)	Final setting For VBW (kHz)
11AX20MIMO	0.56	0.916	0.6114	61.14	2.14	1.79	2
11AX40MIMO	0.32	0.705	0.4539	45.39	3.43	3.13	3.3
11AX80MIMO	0.196	0.5785	0.3388	33.88	4.70	5.10	5.1

Note:
Duty Cycle Correction Factor=10log (1/x).
Where: x is Duty Cycle (Linear)
Where: T is On Time
If that calculated VBW is not available on the analyzer then the next higher value should be used.

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.