UL Solutions

Tx. Spurious NVNT g 2462MHz Ant6 Emission

Tx. Spurious NVNT n20 2412MHz Ant7 Ref

Tx. Spurious NVNT n20 2412MHz Ant7 Emission

UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch   FORM NO: 10-SL-F0035

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

Tx. Spurious NVNT n20 2412MHz Ant6 Ref

Tx. Spurious NVNT n20 2412MHz Ant6 Emission

Tx. Spurious NVNT n20 2437MHz Ant7 Ref

UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch   FORM NO: 10-SL-F0035

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

Tx. Spurious NVNT n20 2437MHz Ant7 Emission

Tx. Spurious NVNT n20 2437MHz Ant6 Ref

Tx. Spurious NVNT n20 2437MHz Ant6 Emission

UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch   FORM NO: 10-SL-F0035

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

Tx. Spurious NVNT n20 2462MHz Ant7 Ref

Tx. Spurious NVNT n20 2462MHz Ant7 Emission

Tx. Spurious NVNT n20 2462MHz Ant6 Ref

UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch   FORM NO: 10-SL-F0035

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

Tx. Spurious NVNT n20 2462MHz Ant6 Emission

Tx. Spurious NVNT n40 2422MHz Ant7 Ref

Tx. Spurious NVNT n40 2422MHz Ant7 Emission

UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch   FORM NO: 10-SL-F0035

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

Tx. Spurious NVNT n40 2422MHz Ant6 Ref

Tx. Spurious NVNT n40 2422MHz Ant6 Emission

Tx. Spurious NVNT n40 2437MHz Ant7 Ref

UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch   FORM NO: 10-SL-F0035

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

Tx. Spurious NVNT n40 2437MHz Ant7 Emission

Tx. Spurious NVNT n40 2437MHz Ant6 Ref

Tx. Spurious NVNT n40 2437MHz Ant6 Emission

Tx. Spurious NVNT n40 2452MHz Ant7 Ref

Tx. Spurious NVNT n40 2452MHz Ant7 Emission

Tx. Spurious NVNT n40 2452MHz Ant6 Ref

UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch   FORM NO: 10-SL-F0035

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

Tx. Spurious NVNT n40 2452MHz Ant6 Emission

Tx. Spurious NVNT ax20 2412MHz Ant7 Ref

Tx. Spurious NVNT ax20 2412MHz Ant7 Emission

UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch   FORM NO: 10-SL-F0035

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

Tx. Spurious NVNT ax20 2412MHz Ant6 Ref

Tx. Spurious NVNT ax20 2412MHz Ant6 Emission

Tx. Spurious NVNT ax20 2437MHz Ant7 Ref

UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch   FORM NO: 10-SL-F0035

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

Tx. Spurious NVNT ax20 2437MHz Ant7 Emission

Tx. Spurious NVNT ax20 2437MHz Ant6 Ref

Tx. Spurious NVNT ax20 2437MHz Ant6 Emission

UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch   FORM NO: 10-SL-F0035

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

Tx. Spurious NVNT ax20 2462MHz Ant7 Ref

Tx. Spurious NVNT ax20 2462MHz Ant7 Emission

Tx. Spurious NVNT ax20 2462MHz Ant6 Ref

UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch   FORM NO: 10-SL-F0035

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

Tx. Spurious NVNT ax20 2462MHz Ant6 Emission

Tx. Spurious NVNT ax40 2422MHz Ant7 Ref

Tx. Spurious NVNT ax40 2422MHz Ant7 Emission

UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch   FORM NO: 10-SL-F0035

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

Tx. Spurious NVNT ax40 2422MHz Ant6 Ref

Tx. Spurious NVNT ax40 2422MHz Ant6 Emission

Tx. Spurious NVNT ax40 2437MHz Ant7 Ref

UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch   FORM NO: 10-SL-F0035

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

Tx. Spurious NVNT ax40 2437MHz Ant7 Emission

Tx. Spurious NVNT ax40 2437MHz Ant6 Ref

Tx. Spurious NVNT ax40 2437MHz Ant6 Emission

UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch   FORM NO: 10-SL-F0035

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

Tx. Spurious NVNT ax40 2452MHz Ant7 Ref

Tx. Spurious NVNT ax40 2452MHz Ant7 Emission

Tx. Spurious NVNT ax40 2452MHz Ant6 Ref

UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch   FORM NO: 10-SL-F0035

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

Tx. Spurious NVNT ax40 2452MHz Ant6 Emission

END OF REPORT

UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch   FORM NO: 10-SL-F0035

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.