OBW NVNT n20 5180MHz Ant8



OBW NVNT n20 5200MHz Ant6



OBW NVNT n20 5200MHz Ant8



This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

OBW NVNT n20 5240MHz Ant6



OBW NVNT n20 5240MHz Ant8



OBW NVNT n20 5260MHz Ant6



This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

OBW NVNT n20 5260MHz Ant8



OBW NVNT n20 5280MHz Ant6



OBW NVNT n20 5280MHz Ant8



This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

OBW NVNT n20 5320MHz Ant6



OBW NVNT n20 5320MHz Ant8



OBW NVNT n20 5500MHz Ant6



This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

OBW NVNT n20 5500MHz Ant8



OBW NVNT n20 5580MHz Ant6



OBW NVNT n20 5580MHz Ant8



This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

OBW NVNT n20 5700MHz Ant6



OBW NVNT n20 5700MHz Ant8



OBW NVNT n20 5720MHz Ant6



This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

OBW NVNT n20 5720MHz Ant8



OBW NVNT n20 5745MHz Ant6



OBW NVNT n20 5745MHz Ant8



This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

OBW NVNT n20 5785MHz Ant6



OBW NVNT n20 5785MHz Ant8



OBW NVNT n20 5825MHz Ant6



This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

OBW NVNT n20 5825MHz Ant8



OBW NVNT n40 5190MHz Ant6



OBW NVNT n40 5190MHz Ant8



This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

OBW NVNT n40 5230MHz Ant6



OBW NVNT n40 5230MHz Ant8



OBW NVNT n40 5270MHz Ant6



This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

OBW NVNT n40 5270MHz Ant8



OBW NVNT n40 5310MHz Ant6



OBW NVNT n40 5310MHz Ant8



This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

OBW NVNT n40 5510MHz Ant6



OBW NVNT n40 5510MHz Ant8



OBW NVNT n40 5550MHz Ant6



This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

OBW NVNT n40 5550MHz Ant8



OBW NVNT n40 5670MHz Ant6



OBW NVNT n40 5670MHz Ant8



This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

OBW NVNT n40 5710MHz Ant6



OBW NVNT n40 5710MHz Ant8



OBW NVNT n40 5755MHz Ant6



This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

OBW NVNT n40 5755MHz Ant8



OBW NVNT n40 5785MHz Ant6



OBW NVNT n40 5785MHz Ant8



This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

OBW NVNT n40 5795MHz Ant6



OBW NVNT n40 5795MHz Ant8



OBW NVNT ac80 5210MHz Ant6



This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

OBW NVNT ac80 5210MHz Ant8



OBW NVNT ac80 5290MHz Ant6



OBW NVNT ac80 5290MHz Ant8



This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

OBW NVNT ac80 5530MHz Ant6



OBW NVNT ac80 5530MHz Ant8



OBW NVNT ac80 5610MHz Ant6



This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

OBW NVNT ac80 5610MHz Ant8



OBW NVNT ac80 5690MHz Ant6



OBW NVNT ac80 5690MHz Ant8



This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

OBW NVNT ac80 5775MHz Ant6



OBW NVNT ac80 5775MHz Ant8



OBW NVNT ax20 5180MHz Ant6



This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

OBW NVNT ax20 5180MHz Ant8



OBW NVNT ax20 5200MHz Ant6



OBW NVNT ax20 5200MHz Ant8



This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

OBW NVNT ax20 5240MHz Ant6



OBW NVNT ax20 5240MHz Ant8



OBW NVNT ax20 5260MHz Ant6



This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

OBW NVNT ax20 5260MHz Ant8



OBW NVNT ax20 5280MHz Ant6



OBW NVNT ax20 5280MHz Ant8



This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

OBW NVNT ax20 5320MHz Ant6



OBW NVNT ax20 5320MHz Ant8



OBW NVNT ax20 5500MHz Ant6



This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

OBW NVNT ax20 5500MHz Ant8



OBW NVNT ax20 5580MHz Ant6



OBW NVNT ax20 5580MHz Ant8



This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

OBW NVNT ax20 5700MHz Ant6



OBW NVNT ax20 5700MHz Ant8



OBW NVNT ax20 5720MHz Ant6



This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

OBW NVNT ax20 5720MHz Ant8



OBW NVNT ax20 5745MHz Ant6



OBW NVNT ax20 5745MHz Ant8



This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

OBW NVNT ax20 5785MHz Ant6



OBW NVNT ax20 5785MHz Ant8



OBW NVNT ax20 5825MHz Ant6



This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.