Difference Information

The difference between
HT800-LM0Q-GL, HT801-LM0Q-GL, and FT700-LM0Q-GL, are as follows:

SOFTWARE MODIFICATIONS: NO
Antenna: NO
Power Input: NO
HARDWARE MODIFICATION:
    The followings are different

Model Name	IP Rating	Battery capacity	Buzzer
FT700-LM0Q-GL	IP4X	1.3Ah	Y
HT801-LM0Q-GL	IP67	6Ah	N
HT800-LM0Q-GL	IP67	6Ah	N

Model Name	Ultracap	Digital Outputs	Tamper proof cover w switch
FT700-LM0Q-GL	N	3	Y
HT801-LM0Q-GL	N	4	N
HT800-LM0Q-GL	Y	4	N

The others: NO

The RF modem are all the same for the 3models.
The Radiated data indicated the worst of the 3models.

Signature:

Print name: Nina Wang

Date: 2020/1/7

Company: Flex Industrial, Ltd.

Address: Level 3, Alexander House, 35 Cybercity, Ebene, Mauritius
Tel: 13917144740

Email: Nina.Wang@flex.com