No label will be used to mark the FCC ID on the module due to space constraints as explained in the original filing for FCC ID: VPYLB1DX on 4/27/16. This applies identically for FCC ID 2AQ8D3. The FCC ID will be identified in the associated user manual.