11AX80MIMO_Ant1_6705_High_6670_10


11AX80MIMO_Ant1_6705_Center_6705_1

11AX80MIMO_Ant1_6705_Center_6705_2

11AX80MIMO_Ant1_6705_Center_6705_3

11AX80MIMO_Ant1_6705_Center_6705_4


11AX80MIMO_Ant1_6705_Center_6705_5

11AX80MIMO_Ant1_6705_Center_6705_6

11AX80MIMO_Ant1_6705_Center_6705_7

11AX80MIMO_Ant1_6705_Center_6705_8

11AX80MIMO_Ant1_6705_Center_6705_9

UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch   FORM No.: 10-SL-F0089

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

11AX80MIMO_Ant1_6705_Center_6705_10

11AX80MIMO_Ant1_6705_Low_6740_1

11AX80MIMO_Ant1_6705_Low_6740_2

11AX80MIMO_Ant1_6705_Low_6740_3

UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch   FORM No.: 10-SL-F0089

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

11AX80MIMO_Ant1_6705_Low_6740_4

11AX80MIMO_Ant1_6705_Low_6740_5

11AX80MIMO_Ant1_6705_Low_6740_6

11AX80MIMO_Ant1_6705_Low_6740_7

UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch   FORM No.: 10-SL-F0089

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

11AX80MIMO_Ant1_6705_Low_6740_8

11AX80MIMO_Ant1_6705_Low_6740_9

UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch   FORM No.: 10-SL-F0089

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

11AX80MIMO_Ant1_6705_Low_6740_10


11AX80MIMO_Ant1_6945_High_6910_1

11AX80MIMO_Ant1_6945_High_6910_2

11AX80MIMO_Ant1_6945_High_6910_3

11AX80MIMO_Ant1_6945_High_6910_4

11AX80MIMO_Ant1_6945_High_6910_5

UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch   FORM No.: 10-SL-F0089

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

11AX80MIMO_Ant1_6945_High_6910_6

11AX80MIMO_Ant1_6945_High_6910_7

11AX80MIMO_Ant1_6945_High_6910_8

11AX80MIMO_Ant1_6945_High_6910_9

UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch   FORM No.: 10-SL-F0089

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

11AX80MIMO_Ant1_6945_High_6910_10


11AX80MIMO_Ant1_6945_Center_6945_1

11AX80MIMO_Ant1_6945_Center_6945_2

11AX80MIMO_Ant1_6945_Center_6945_3

11AX80MIMO_Ant1_6945_Center_6945_4


11AX80MIMO_Ant1_6945_Center_6945_5

11AX80MIMO_Ant1_6945_Center_6945_6

11AX80MIMO_Ant1_6945_Center_6945_7

UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch   FORM No.: 10-SL-F0089

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

11AX80MIMO_Ant1_6945_Center_6945_8

11AX80MIMO_Ant1_6945_Center_6945_9

11AX80MIMO_Ant1_6945_Center_6945_10


11AX80MIMO_Ant1_6945_Low_6980_1

11AX80MIMO_Ant1_6945_Low_6980_2

11AX80MIMO_Ant1_6945_Low_6980_3

11AX80MIMO_Ant1_6945_Low_6980_4

11AX80MIMO_Ant1_6945_Low_6980_5

UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch   FORM No.: 10-SL-F0089

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

11AX80MIMO_Ant1_6945_Low_6980_6

11AX80MIMO_Ant1_6945_Low_6980_7

UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch   FORM No.: 10-SL-F0089

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

11AX80MIMO_Ant1_6945_Low_6980_8

11AX80MIMO_Ant1_6945_Low_6980_9

UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch   FORM No.: 10-SL-F0089

*This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.*

11AX80MIMO_Ant1_6945_Low_6980_10

_____

END OF REPORT