Temperature & Humidity Smart Sensor

INSTRUCTION

Main Function

✓ Real-time monitoring temperature and humidity.

✓ Push notifications when the temperature or humidity exceed the limits.

✓ Calibrate temperature and humidity.

✓ Chart graph display.

✓ Save and export data.

✓ Kinds of accessories for easily installation.

Contents of Package

✓ Sensor x1
✓ Lanyard x1
✓ Back clip x1
✓ 3M tape x1
✓ Bracket x1

Specifications

Battery: CR2477 3V 1000mAH

Standby current: ≤3uA

Protocol: bluetooth5.0

Wireless Range: 50m

Operating Temperature: -20℃ ~ 85℃ (-4°F ~ 185°F)

Operating Humidity: 0% ~ 95%

Temperature Accuracy: ±0.3℃ ~ ±1.2℃ / (±0.5°F ~ ±2.2°F)

Humidity Accuracy: ±3% ~ ±5%

Working time: About 18 months

Wireless Type : 2.4GHz

**Size:** 46mm x46mm x15 mm

Download App

✓ Download "SensorPro" app from app store or google paly.

Add Device

1. Remove the battery insulation sheet of the sensor;
2. Run "SensorPro" app on your smart phone ;
3. Take the device close to your phone;
4. Click "+" to add device to app;

Device setting

1. Click the device item on the gray area to go to device setting;
2. Click the camera icon to customize your scenes picture.
3. Click Delete button to remove the device.

Chart display

Click the data area on the device item to show the history data chart.

Unit Switching

Click ☰ to go App setting screen.

The temperature unit can be set as Fahrenheit(°F) or Celsius (℃).

Accessories

Kinds of accessories to help you to install the device in different scenes.