Assembly

Amount	PN	Description
1	6043-1900-3502	Ambient Sensor (T/RH/Light/CO2)
1	6043-2100-8900	Ambient Sensor + CO2 – Certification Label

Place the Label in designated pocket in the Battery Cover.

Make sure the Label is placed in the pocket and is aligned.

Make sure the model number ends with **13**