OBW NVNT n20 5500MHz Ant4



OBW NVNT n20 5580MHz Ant3



OBW NVNT n20 5580MHz Ant4



This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

OBW NVNT n20 5700MHz Ant3



OBW NVNT n20 5700MHz Ant4



This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

OBW NVNT n20 5745MHz Ant3



OBW NVNT n20 5745MHz Ant4



This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

OBW NVNT n20 5785MHz Ant3



OBW NVNT n20 5785MHz Ant4



OBW NVNT n20 5825MHz Ant3



This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

OBW NVNT n20 5825MHz Ant4



OBW NVNT n40 5190MHz Ant3



OBW NVNT n40 5190MHz Ant4



This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

OBW NVNT n40 5230MHz Ant3



OBW NVNT n40 5230MHz Ant4



OBW NVNT n40 5270MHz Ant3



This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

OBW NVNT n40 5270MHz Ant4



OBW NVNT n40 5310MHz Ant3



OBW NVNT n40 5310MHz Ant4



This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

OBW NVNT n40 5510MHz Ant3



OBW NVNT n40 5510MHz Ant4



OBW NVNT n40 5550MHz Ant3



This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

OBW NVNT n40 5550MHz Ant4



OBW NVNT n40 5670MHz Ant3



OBW NVNT n40 5670MHz Ant4



This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

OBW NVNT n40 5755MHz Ant3



This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

OBW NVNT n40 5755MHz Ant4



OBW NVNT n40 5795MHz Ant3



OBW NVNT n40 5795MHz Ant4



This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

OBW NVNT ac80 5210MHz Ant3



OBW NVNT ac80 5210MHz Ant4



OBW NVNT ac80 5290MHz Ant3



This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

OBW NVNT ac80 5290MHz Ant4



OBW NVNT ac80 5530MHz Ant3



OBW NVNT ac80 5530MHz Ant4



This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

OBW NVNT ac80 5610MHz Ant3



OBW NVNT ac80 5610MHz Ant4



This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

OBW NVNT ac80 5775MHz Ant3



OBW NVNT ac80 5775MHz Ant4



This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

OBW NVNT ax20 5180MHz Ant3



OBW NVNT ax20 5180MHz Ant4



OBW NVNT ax20 5200MHz Ant3



This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

OBW NVNT ax20 5200MHz Ant4



OBW NVNT ax20 5240MHz Ant3



OBW NVNT ax20 5240MHz Ant4



This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

OBW NVNT ax20 5260MHz Ant3



OBW NVNT ax20 5260MHz Ant4



OBW NVNT ax20 5280MHz Ant3



This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

OBW NVNT ax20 5280MHz Ant4



OBW NVNT ax20 5320MHz Ant3



OBW NVNT ax20 5320MHz Ant4



This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

OBW NVNT ax20 5500MHz Ant3



OBW NVNT ax20 5500MHz Ant4



OBW NVNT ax20 5580MHz Ant3



This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

OBW NVNT ax20 5580MHz Ant4



OBW NVNT ax20 5700MHz Ant3



OBW NVNT ax20 5700MHz Ant4



This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

OBW NVNT ax20 5745MHz Ant3



This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

OBW NVNT ax20 5745MHz Ant4



OBW NVNT ax20 5785MHz Ant3



OBW NVNT ax20 5785MHz Ant4



This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

OBW NVNT ax20 5825MHz Ant3



OBW NVNT ax20 5825MHz Ant4



OBW NVNT ax40 5190MHz Ant3



This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

OBW NVNT ax40 5190MHz Ant4



OBW NVNT ax40 5230MHz Ant3



OBW NVNT ax40 5230MHz Ant4



This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

OBW NVNT ax40 5270MHz Ant3



OBW NVNT ax40 5270MHz Ant4



OBW NVNT ax40 5310MHz Ant3



This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

OBW NVNT ax40 5310MHz Ant4



OBW NVNT ax40 5510MHz Ant3



OBW NVNT ax40 5510MHz Ant4



This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

OBW NVNT ax40 5550MHz Ant3



OBW NVNT ax40 5550MHz Ant4



OBW NVNT ax40 5670MHz Ant3



This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

OBW NVNT ax40 5670MHz Ant4



This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.