11AC20MIMO_Ant4_5745

11AC20MIMO_Ant1_5785

11AC20MIMO_Ant2_5785

UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch   FORM NO: 10-SL-F0035

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

UL Solutions

Date: 20.JUN.2024 11:17:59

11AC20MIMO_Ant3_5785

Date: 20.JUN.2024 11:18:07

11AC20MIMO_Ant4_5785

Date: 20.JUN.2024 11:18:35

11AC20MIMO_Ant1_5825

11AC20MIMO_Ant2_5825

11AC20MIMO_Ant3_5825

11AC20MIMO_Ant4_5825

UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch   FORM NO: 10-SL-F0035

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

11AC40MIMO_Ant1_5190

11AC40MIMO_Ant2_5190

11AC40MIMO_Ant3_5190

UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch   FORM NO: 10-SL-F0035

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

11AC40MIMO_Ant4_5190

11AC40MIMO_Ant1_5230

11AC40MIMO_Ant2_5230

UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch   FORM NO: 10-SL-F0035

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

11AC40MIMO_Ant3_5230

11AC40MIMO_Ant4_5230

11AC40MIMO_Ant1_5270

UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch   FORM NO: 10-SL-F0035

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

11AC40MIMO_Ant2_5270

11AC40MIMO_Ant3_5270

11AC40MIMO_Ant4_5270

UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch   FORM NO: 10-SL-F0035

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

11AC40MIMO_Ant1_5310

11AC40MIMO_Ant2_5310

11AC40MIMO_Ant3_5310

11AC40MIMO_Ant4_5310

11AC40MIMO_Ant1_5510

11AC40MIMO_Ant2_5510

UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch   FORM NO: 10-SL-F0035

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

11AC40MIMO_Ant3_5510


11AC40MIMO_Ant4_5510

11AC40MIMO_Ant1_5550

11AC40MIMO_Ant2_5550


11AC40MIMO_Ant3_5550

11AC40MIMO_Ant4_5550

UL Solutions

Spectrum

Ref Level 35.00 dBm Offset 25.08 dB RBW 500 kHz
Att   30 dB   SWT   1 ms VBW 2 MHz   Mode Auto Sweep
Count 100/100
1Pk View

M1[1] -18.83 dBm 5.6498400 GHz
M2[1]   8.39 dBm 5.6718400 GHz

D1 -17.610 dBm

CF 5.67 GHz   1001 pts   Span 80.0 MHz

Marker
Type	Ref	Trc	X-value	Y-value	Function	Function Result
M1		1	5.64984 GHz	-18.83 dBm		
M2		1	5.67184 GHz	8.39 dBm		
D3	M1	1	40.32 MHz	0.49 dB		

Date: 18.JUN.2024 06:10:19

11AC40MIMO_Ant1_5670

Spectrum

Ref Level 35.00 dBm Offset 25.04 dB RBW 500 kHz
Att   30 dB   SWT   1 ms VBW 2 MHz   Mode Auto Sweep
Count 100/100
1Pk View

M1[1] -18.83 dBm 5.6499200 GHz
M2[1]   8.83 dBm 5.6626400 GHz

D1 -17.170 dBm

CF 5.67 GHz   1001 pts   Span 80.0 MHz

Marker
Type	Ref	Trc	X-value	Y-value	Function	Function Result
M1		1	5.64992 GHz	-18.83 dBm		
M2		1	5.66264 GHz	8.83 dBm		
D3	M1	1	40.08 MHz	1.20 dB		

Date: 18.JUN.2024 06:10:58

11AC40MIMO_Ant2_5670

Spectrum

Ref Level 35.00 dBm Offset 25.06 dB RBW 500 kHz
Att   30 dB   SWT   1 ms VBW 2 MHz   Mode Auto Sweep
Count 100/100
1Pk View

M1[1] -21.69 dBm 5.6496800 GHz
M2[1]   5.65 dBm 5.6594400 GHz

D1 -20.350 dBm

CF 5.67 GHz   1001 pts   Span 80.0 MHz

Marker
Type	Ref	Trc	X-value	Y-value	Function	Function Result
M1		1	5.64968 GHz	-21.69 dBm		
M2		1	5.65944 GHz	5.65 dBm		
D3	M1	1	40.56 MHz	0.50 dB		

Date: 18.JUN.2024 06:11:49

11AC40MIMO_Ant3_5670

11AC40MIMO_Ant4_5670

11AC40MIMO_Ant1_5755

11AC40MIMO_Ant2_5755

UL Solutions

**11AC40MIMO_Ant3_5755**

11AC40MIMO_Ant4_5755

**11AC40MIMO_Ant1_5795**

11AC40MIMO_Ant2_5795

11AC40MIMO_Ant3_5795

11AC40MIMO_Ant4_5795

11AC80MIMO_Ant1_5210


11AC80MIMO_Ant2_5210

11AC80MIMO_Ant3_5210

11AC80MIMO_Ant4_5210


11AC80MIMO_Ant1_5290


11AC80MIMO_Ant2_5290

11AC80MIMO_Ant3_5290

11AC80MIMO_Ant4_5290

11AC80MIMO_Ant1_5530

Date: 25.JUN.2024 13:40:19

11AC80MIMO_Ant2_5530

Date: 25.JUN.2024 13:42:50

11AC80MIMO_Ant3_5530

Date: 25.JUN.2024 13:43:42

11AC80MIMO_Ant4_5530

Date: 18.JUN.2024 08:49:47

11AC80MIMO_Ant1_5610

Date: 18.JUN.2024 08:50:26

11AC80MIMO_Ant2_5610

Date: 18.JUN.2024 08:51:18

11AC80MIMO_Ant3_5610

Date: 18.JUN.2024 08:52:09

11AC80MIMO_Ant4_5610

Date: 20.JUN.2024 13:29:41

11AC80MIMO_Ant1_5775

Date: 20.JUN.2024 13:29:49

11AC80MIMO_Ant2_5775

UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch   FORM NO: 10-SL-F0035

*This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.*

11AC80MIMO_Ant3_5775

11AC80MIMO_Ant4_5775

11AC160MIMO_Ant1_5250

11AC160MIMO_Ant2_5250

11AC160MIMO_Ant3_5250

11AC160MIMO_Ant4_5250

11AC160MIMO_Ant1_5570

11AC160MIMO_Ant2_5570

11AC160MIMO_Ant3_5570

UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch   FORM NO: 10-SL-F0035

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

UL Solutions

11AC160MIMO_Ant4_5570

11AX20MIMO_Ant1_5180

11AX20MIMO_Ant2_5180

UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch   FORM NO: 10-SL-F0035

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

11AX20MIMO_Ant3_5180

11AX20MIMO_Ant4_5180

11AX20MIMO_Ant1_5200

11AX20MIMO_Ant2_5200

11AX20MIMO_Ant3_5200

11AX20MIMO_Ant4_5200

11AX20MIMO_Ant1_5240

11AX20MIMO_Ant2_5240

11AX20MIMO_Ant3_5240

UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch   FORM NO: 10-SL-F0035

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

11AX20MIMO_Ant4_5240

11AX20MIMO_Ant1_5260

11AX20MIMO_Ant2_5260

UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch   FORM NO: 10-SL-F0035

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

11AX20MIMO_Ant3_5260

11AX20MIMO_Ant4_5260

11AX20MIMO_Ant1_5280

UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch   FORM NO: 10-SL-F0035

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.

UL Solutions

Date: 20.JUN.2024 14:23:12

11AX20MIMO_Ant2_5280

Date: 20.JUN.2024 14:24:03

11AX20MIMO_Ant3_5280

Date: 20.JUN.2024 14:24:45

11AX20MIMO_Ant4_5280

11AX20MIMO_Ant1_5320

11AX20MIMO_Ant2_5320

11AX20MIMO_Ant3_5320

11AX20MIMO_Ant4_5320

11AX20MIMO_Ant1_5500

11AX20MIMO_Ant2_5500

UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch   FORM NO: 10-SL-F0035

*This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.*

11AX20MIMO_Ant3_5500

11AX20MIMO_Ant4_5500

11AX20MIMO_Ant1_5580

Date: 20.JUN.2024 14:34:37

11AX20MIMO_Ant2_5580

Date: 20.JUN.2024 14:35:28

11AX20MIMO_Ant3_5580

Date: 20.JUN.2024 14:36:10

11AX20MIMO_Ant4_5580

UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch   FORM NO: 10-SL-F0035

This report shall not be reproduced except in full, without the written approval of UL Verification Services (Guangzhou) Co., Ltd, Song Shan Lake Branch.