

LTE B41 15MHz + 10MHz QPSK Low Ch RB1-0 + RB1-49



LTE B41 15MHz + 10MHz QPSK Low Ch RB75-0 + RB50-0



LTE B41 15MHz + 10MHz QPSK Mid Ch RB1-0 + RB1-49



LTE B41 15MHz + 10MHz QPSK Mid Ch RB75-0 + RB50-0



LTE B41 15MHz + 10MHz QPSK High Ch RB1-0 + RB1-49



LTE B41 15MHz + 10MHz QPSK High Ch RB75-0 + RB50-0

UL Korea, Ltd. Suwon Laboratory FORM ID: FCC_22/24/27(04)
218 Maeyeong-ro, Yeongtong-gu, Suwon-si, Gyeonggi-do, 16675, Korea TEL: (031) 337-9902 FAX: (031) 213-5433

UL Korea, Ltd. Confidential
This report shall not be reproduced except in full, without the written approval of UL Korea, Ltd.



LTE B41 15MHz + 10MHz 16QAM Low Ch RB1-0 + RB1-49

LTE B41 15MHz + 10MHz 16QAM Low Ch RB75-0 + RB50-0



LTE B41 15MHz + 10MHz 16QAM Mid Ch RB1-0 + RB1-49



LTE B41 15MHz + 10MHz 16QAM Mid Ch RB75-0 + RB50-0



LTE B41 15MHz + 10MHz 16QAM High Ch RB1-0 + RB1-49



LTE B41 15MHz + 10MHz 16QAM High Ch RB75-0 + RB50-0

UL Korea, Ltd. Confidential
This report shall not be reproduced except in full, without the written approval of UL Korea, Ltd.



LTE B41 10MHz + 20MHz QPSK Low Ch RB1-0 + RB1-99



LTE B41 10MHz + 20MHz QPSK Low Ch RB50-0 + RB100-0



LTE B41 10MHz + 20MHz QPSK Mid Ch RB1-0 + RB1-99



LTE B41 10MHz + 20MHz QPSK Mid Ch RB50-0 + RB100-0



LTE B41 10MHz + 20MHz QPSK High Ch RB1-0 + RB1-99



LTE B41 10MHz + 20MHz QPSK High Ch RB50-0 + RB100-0

UL Korea, Ltd. Suwon Laboratory FORM ID: FCC_22/24/27(04)
218 Maeyeong-ro, Yeongtong-gu, Suwon-si, Gyeonggi-do, 16675, Korea TEL: (031) 337-9902 FAX: (031) 213-5433

UL Korea, Ltd. Confidential
This report shall not be reproduced except in full, without the written approval of UL Korea, Ltd.



LTE B41 10MHz + 20MHz 16QAM Low Ch RB1-0 + RB1-99



LTE B41 10MHz + 20MHz 16QAM Low Ch RB50-0 + RB100-0



LTE B41 10MHz + 20MHz 16QAM Mid Ch RB1-0 + RB1-99



LTE B41 10MHz + 20MHz 16QAM Mid Ch RB50-0 + RB100-0



LTE B41 10MHz + 20MHz 16QAM High Ch RB1-0 + RB1-99



LTE B41 10MHz + 20MHz 16QAM High Ch RB50-0 + RB100-0

UL Korea, Ltd. Confidential
This report shall not be reproduced except in full, without the written approval of UL Korea, Ltd.



LTE B41 20MHz + 10MHz QPSK Low Ch RB1-0 + RB1-49



LTE B41 20MHz + 10MHz QPSK Low Ch RB100-0 + RB50-0



LTE B41 20MHz + 10MHz QPSK Mid Ch RB1-0 + RB1-49



LTE B41 20MHz + 10MHz QPSK Mid Ch RB100-0 + RB50-0



LTE B41 20MHz + 10MHz QPSK High Ch RB1-0 + RB1-49



LTE B41 20MHz + 10MHz QPSK High Ch RB100-0 + RB50-0

UL Korea, Ltd. Suwon Laboratory FORM ID: FCC_22/24/27(04)
218 Maeyeong-ro, Yeongtong-gu, Suwon-si, Gyeonggi-do, 16675, Korea TEL: (031) 337-9902 FAX: (031) 213-5433

UL Korea, Ltd. Confidential
This report shall not be reproduced except in full, without the written approval of UL Korea, Ltd.



LTE B41 20MHz + 10MHz 16QAM Low Ch RB1-0 + RB1-49



LTE B41 20MHz + 10MHz 16QAM Low Ch RB100-0 + RB50-0



LTE B41 20MHz + 10MHz 16QAM Mid Ch RB1-0 + RB1-49



LTE B41 20MHz + 10MHz 16QAM Mid Ch RB100-0 + RB50-0



LTE B41 20MHz + 10MHz 16QAM High Ch RB1-0 + RB1-49



LTE B41 20MHz + 10MHz 16QAM High Ch RB100-0 + RB50-0

UL Korea, Ltd. Suwon Laboratory FORM ID: FCC_22/24/27(04)
218 Maeyeong-ro, Yeongtong-gu, Suwon-si, Gyeonggi-do, 16675, Korea TEL: (031) 337-9902 FAX: (031) 213-5433
UL Korea, Ltd. Confidential
This report shall not be reproduced except in full, without the written approval of UL Korea, Ltd.



LTE B41 15MHz + 15MHz QPSK Low Ch RB1-0 + RB1-74

LTE B41 15MHz + 15MHz QPSK Low Ch RB75-0 + RB75-0



LTE B41 15MHz + 15MHz QPSK Mid Ch RB1-0 + RB1-74



LTE B41 15MHz + 15MHz QPSK Mid Ch RB75-0 + RB75-0



LTE B41 15MHz + 15MHz QPSK High Ch RB1-0 + RB1-74



LTE B41 15MHz + 15MHz QPSK High Ch RB75-0 + RB75-0

UL Korea, Ltd. Suwon Laboratory FORM ID: FCC_22/24/27(04)
218 Maeyeong-ro, Yeongtong-gu, Suwon-si, Gyeonggi-do, 16675, Korea TEL: (031) 337-9902 FAX: (031) 213-5433

UL Korea, Ltd. Confidential
This report shall not be reproduced except in full, without the written approval of UL Korea, Ltd.



LTE B41 15MHz + 15MHz 16QAM Low Ch RB1-0 + RB1-74



LTE B41 15MHz + 15MHz 16QAM Low Ch RB75-0 + RB75-0



LTE B41 15MHz + 15MHz 16QAM Mid Ch RB1-0 + RB1-74



LTE B41 15MHz + 15MHz 16QAM Mid Ch RB75-0 + RB75-0



LTE B41 15MHz + 15MHz 16QAM High Ch RB1-0 + RB1-74



LTE B41 15MHz + 15MHz 16QAM High Ch RB75-0 + RB75-0

UL Korea, Ltd. Confidential
This report shall not be reproduced except in full, without the written approval of UL Korea, Ltd.



LTE B41 15MHz + 20MHz QPSK Low Ch RB1-0 + RB1-99

LTE B41 15MHz + 20MHz QPSK Low Ch RB75-0 + RB100-0



LTE B41 15MHz + 20MHz QPSK Mid Ch RB1-0 + RB1-99



LTE B41 15MHz + 20MHz QPSK Mid Ch RB75-0 + RB100-0



LTE B41 15MHz + 20MHz QPSK High Ch RB1-0 + RB1-99



LTE B41 15MHz + 20MHz QPSK High Ch RB75-0 + RB100-0

UL Korea, Ltd. Suwon Laboratory FORM ID: FCC_22/24/27(04)
218 Maeyeong-ro, Yeongtong-gu, Suwon-si, Gyeonggi-do, 16675, Korea TEL: (031) 337-9902 FAX: (031) 213-5433
UL Korea, Ltd. Confidential
This report shall not be reproduced except in full, without the written approval of UL Korea, Ltd.